

Nowość!



• Spot Repair Puller with Accessories

APP No. 351550

Spot repair puller is an universal device purposed for dent repairs without application of top coat. It features with wide adjustment range of supports and tang that enables its use on any type of surface. Holding and closing puller handle results in tang upward movement. In addition precise control of pulling height is ensured. Puller is provided with spot electrode for dent pulling, spotter adapter and the handle for noninvasive pulling of dents with use of tabs glued to the top coat. Made from steel and coated aluminum.



Kit includes:



APP No. 351555 Spot electrode for minor dents pulling, purposed for use with PULLER 251550. It enables repairs of small dents after direct connection to spotter. For any repairs the following are required: 351558 and 351560.



APP No. 351558 Electrode adapter 351555 that enables mounting of 351555 electrode to PULLER 351550.



APP No. 351560 Adapter enabling connection of 351550 PULLER to the spotter (welding device) or welding gun. To be mounted on the top part of 351558 and 351560 pulling tang.



APP No. 351552. Tab handle. Purposed for repairs provided with hot adhesive. To be mounted on 351550 PULLER or 351611 pulling beam tang or 351620. M10 thread. Made from aluminum.

APP No.	Name	Packaging
351550	Puller with accessories	1 item

APP Sp. z o.o.

ul. Przemysłowa 10, 62-300 Września

Customer Service Department: Phone 061/437 00 20, fax 061/437 00 21

APP
AUTO-PLAST PRODUKT

18.01.2013r.